

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K 0000  Bldg. 01	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 09/10/15</p> <p>Facility Number: 000230 Provider Number: 155524 AIM Number: 100275000</p> <p>At this Life Safety Code survey, Health Center At Glenburn Home was found in substantial compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors, spaces open to the corridors, and resident sleeping rooms in the 400 north hall, 500 north hall, 600 hall, and 700 hall, and 700 rehabilitation</p>		K 0000	<p>By submitting the enclosed material we are not admitting the truth or accuracy of any specific findings or allegations. We reserve the right to contest the findings or allegations as part of any proceedings and submit these responses pursuant to our regulatory obligations. The facility request the plan of correction be considered our allegation of compliance effective September 28, 2015 to the state findings of the Life Safety Code Recertification and State Licensure Survey conducted on September 10, 2015.</p>			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 0018 SS=B Bldg. 01	<p>suite rooms, plus battery operated smoke detectors in the 300 south hall, 400 south hall, 500 south hall and all Special Care Unit resident sleeping rooms, including the 100 and 200 halls. The facility has a capacity of 149 and had a census of 130 at the time of this survey.</p> <p>All areas where residents have customary access were sprinklered and all areas providing facility services were sprinklered, except an attached structure used as a maintenance shop and storage room separated from the facility by a two hour fire wall, and one detached garage used for facility storage.</p> <p>Quality Review completed 09/15/15 - DA</p> <p>NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1¾ inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3</p> <p>Roller latches are prohibited by CMS regulations in all health care facilities.</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
	<p>Based on observation and interview, the facility failed to ensure 1 of 1 sets of double doors to the corridor were equipped with positive latches and latched into the door frame. This deficient practice could affect any number of residents, as well as staff and visitors while in the Friendly Grove Hall and adjoining halls which pass through this area.</p> <p>Findings include:</p> <p>Based on observation on 09/10/15 at 12:15 p.m. during a tour of the facility with Maintenance Supervisor, the set of double doors to the Friendly Grove Hall clean linen closet were sliding doors which did not latch into the door frame. This was acknowledged by Maintenance Supervisor at the time of observation.</p> <p>3.1-19(b)</p>		K 0018	<p>The corrective action taken for those residents found to be affected by the deficient practice is that the sliding double doors identified during the survey on the linen closet of the Friendly Grove Unit have been replaced with framed positive latched doors.</p> <p>The corrective action taken for the other residents having the potential to be affected by the same deficient practice is that a housewide audit has been completed by the maintenance director to determine if there are any other doors that do not meet this requirement. No other doors were identified.</p> <p>The measures or systematic changes that have been put into place to ensure that the deficient practice does not recur is that a mandatory in-service has been provided for the maintenance department staff on the regulation related to acceptable standards related to doors protecting corridor openings requiring positive door latches.</p> <p><i>The corrective action will be monitored to ensure the deficient practice will not recur through the quality assurance program by a Quality Assurance tool has been developed and implemented to monitor the type of doors that are used to protect corridor openings to</i></p>		09/29/2015	

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
					ensure that they meet life safety code standards. This tool will be completed by the Maintenance Supervisor and/or his designee. The tool will be completed weekly for four weeks, then monthly for two months and then quarterly for three quarters. The outcomes will be reviewed at the facility's Quarterly Quality Assurance meeting to determine if any additional action is warranted.		

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K 0144 SS=C Bldg. 01	<p>NFPA 101 LIFE SAFETY CODE STANDARD Generators are inspected weekly and exercised under load for 30 minutes per month in accordance with NFPA 99. 3.4.4.1.</p> <p>1. Based on record review and interview, the facility failed to ensure 2 of 2 emergency generators was inspected and</p>		K 0144	<p>1).The corrective action taken for those residents foundto be affected by the deficient practice is that allresidents have the potential to be</p>		09/29/2015	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>exercised in accordance with NFPA 99. NFPA 99, 3-5.4.2 requires a written record of inspection, performance, exercising period and repairs shall be regularly maintained and available for inspection by the authority having jurisdiction. This deficient practice could affect all residents, as well as staff and visitors in the facility.</p> <p>Findings include:</p> <p>Based on review of the facility's Emergency Generator monthly testing log on 09/10/15 at 10:45 a.m. with the Maintenance Supervisor present, the generator log form documented both generators were tested monthly for 30 minutes under load, however, there was no documentation on the form that showed both generators had cool down times following their load tests. During an interview at the time of record review, the Maintenance Supervisor confirmed the monthly generator log did not include documentation of the cool down times being recorded.</p> <p>3.1-19(b)</p> <p>2. Based on record review and interview, the facility failed to provide complete documentation for the testing of 1 of 2 emergency generators providing power to</p>		<p>affected. The facility is now documenting weekly that each of the facilities two generators are being inspected. The log also reflects that each generator is exercised under load for 30 minutes each month. There is also documentation supporting that the cool down times are recorded on the Emergency Generator Manual Load Test Log.</p> <p>2).The corrective action taken for those residents found to be affected by the deficient practice is that all residents have the potential to be affected by this deficient practice. The facility is now documenting that each emergency generator that provides power to the emergency lighting system is exercised under operating temperature conditions at not less than 30 percent of the EPS (Emergency Power Supply) name plate rating monthly for a minimum of 30 minutes.</p> <p>The corrective action taken for the other residents having the potential to be affected by the same deficient practice is that the facility has revised the log for the Emergency Generator Manual Load Test. The log now includes that each of the facilities two generators are being inspected weekly and that each generator is exercised under load for 30 minutes each month. There is also documentation included to reflect the cool down times</p>				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>the emergency lighting systems. LSC 7.9.2.3 and NFPA 99, Health Care Facilities, 3-4.4.1.1(a) requires monthly testing of the generator set shall be in accordance with NFPA 110, the Standard for Emergency and Standby Power Systems. NFPA 110, 6-4.2 requires generator sets in Level 1 and 2 service shall be exercised under operating temperature conditions or at not less than 30 percent of the EPS (Emergency Power Supply) nameplate rating at least monthly, for a minimum of 30 minutes. NFPA 99, 3-5.4.2 requires a written record of inspection, performance, exercising period and repairs shall be regularly maintained and available for inspection by the authority having jurisdiction. This deficient practice could affect all residents, as well as staff and visitors in the facility.</p> <p>Findings include:</p> <p>Based on review of the facility's Emergency Generator monthly testing log on 09/10/15 at 10:45 p.m. with the Maintenance Supervisor present, the generator log form documented the south generator was tested monthly under load, however, the documentation did not show the generator was exercised under operating temperature conditions or at not less than 30 percent of the EPS</p>		<p>following each generators monthly load test. The log also includes documentation that each generator was exercised under operating temperature conditions or at not less than 30 % of the EPS (Emergency Power Supply) nameplate rating for a minimum of 30 minutes each month.</p> <p>The measures or systematic changes that have been put into place to ensure that the deficient practice does not recur is that the facility has conducted a mandatory in-service for the maintenance department staff on the changes to the emergency generator log and their responsibility in the completion of the log weekly.</p> <p><i>The corrective action will be monitored to ensure the deficient practice will not recur through the quality assurance program by the submission of the completed Emergency Generator Manual Load Test logs to the Quarterly Quality Assurance meeting for review. Additional action will be implemented as deemed warranted by the Quality Assurance Committee. This will be an on-going process.</i></p>				

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>(Emergency Power Supply) nameplate rating for a minimum of 30 minutes during the past twelve months and was under the 30 percent requirement. The generator log form indicated the south generator was load tested at 28 % which did not meet the 30 percent requirement. This was acknowledged by the Maintenance Supervisor at the time of record review.</p> <p>3.1-19(b)</p>						



DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/25/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155524		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/10/2015	
NAME OF PROVIDER OR SUPPLIER  HEALTH CENTER AT GLENBURN HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 618 W GLENBURN ROAD LINTON, IN 47441			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE